



- | | |
|-----------------------------|----------------------|
| 1 - 77 11 064 132 0 | 8 - 77 11 064 203 0 |
| 3 - 77 11 064 361 0 | 9 - 77 11 064 277 0 |
| 4 - 60 01 000 322 * E = 1,0 | 10 - 77 11 064 279 0 |
| 5 - 60 01 000 323 * E = 1,5 | 11 - 77 11 064 280 0 |
| 6 - 60 01 000 324 * E = 2,0 | 12 - 77 11 064 276 0 |
| 7 - 77 03 053 381 A = 1,5 | 13 - 77 11 064 281 0 |
| 77 03 053 014 A = 2,5 | 14 - 77 11 064 205 0 |
| 77 03 053 123 A = 3,5 | 15 - 77 11 064 278 0 |
| 77 03 053 015 A = 4 | 16 - 77 11 064 204 0 |
| | 17 - 77 11 064 202 0 |
| | 18 - 77 11 064 282 0 |
| | 19 - 77 11 064 283 0 |
| | 20 - 77 11 064 673 0 |
| | 21 - 77 11 064 206 0 |
| | 22 - 77 03 034 061 * |
| | 23 - 77 11 064 199 0 |